



Evencure XDS at advanced stages of oxidation .

**Evencure XDS when applied at the recommended application rate, will
Under uv light will begin to oxidise and leave the surface leaving the concrete
In its natural state and colour. The oxidising process takes from 45 to 60 days.**

